

***"Trace & Repair of Commerical Gas Pipe Leak Under Car Park Ground at the Hotel"***

(Photos include some parts of the process : Trace the Gas Leak, Pipe Purging, Replacement of Gas Pipes, Safety Test, Re-Connection of Gas Supply Heating Sytem and all Appliances)

























***"Safety Check and Service on Commercial Heating System"***



***"Replacement of Commercial Gas Flue on Commercial Buidling"***





***"Commercial Fired Pizza Oven & New Flue Installation"***











Examining Plumbing Pipe Under the Ground





Commercial Catering Gas Oven Repair





***New Domestic Boiler Installed***





*"Integrated Domestic Oven Install"*





